Viking Pipe Services Number: MH-050313 to MH-050312A

FIELD VALUE VALUE EIELD 6/4/99 DATE PIPE SIZE 15" X 4' TIME 12:47:59 PM JOINT_TYPE **BELL SPIGOT** UP_DESCRIPT WESTSIDE OF HILL LOCATION ALONG WESTSIDE OF AVE. HILL AVE. DWN_DESCRIPT WESTSIDE OF HILL LENGTH/RUN 162' AVE. MW **INSPECTOR** JOB_# 17-99 FLOW_DIR NORTH CLIENT SUPERIOR, WISC. FLOW_RATE LOW TAPE_# #2 SUPERIOR-MW-99 DIR_MEASURED WITH FLOW COUNTER 00:39:30 ROAD_SURFACE ASPHALT-CONC. SETUP_# #08 MH_REPORT SEE ATTACHED AREA HILL AVE PIPE_TYPE **RCP**

MINOR MINERAL

Comments

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7				START OF RUN #08,THIS IS WITH THE FLOW
15	WATER	1-2"	BOTTOM OF PIPE	
81.8	WATER	2-4"	BOTTOM OF PIPE	
134.1	INFILTRATION AT JOINT	LIGHT		
138.4	INFILTRATION AT JOINT	LIGHT		
142.4	INFILTRATION AT JOINT	LIGHT		
146.5	MINERAL AT JOINT	LIGHT		
150.4	MINERAL AT JOINT	LIGHT		
162				CENTER OF MH-050312A