

Viking Pipe Services
Number: MH-03A307 to MH-03A306A

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	6/7/99	PIPE SIZE	15" X 4'
TIME	1:34:49 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WESTSIDE OF HILL AVE	LOCATION	RUNS ALONG
DWN_DESCRIPTOR	NO. 24TH ST.		WESTSIDE OF HILL AVE
JOB_#	17-99	LENGTH/RUN	264'
CLIENT	SUPERIOR WISC.	INSPECTOR	MW
TAPE_#	#3 SUPERIOR-MW-99	FLOW_DIR	NORTH
COUNTER	00:00:00	FLOW_RATE	LOW
SETUP_#	#03	DIR_MEASURED	WITH FLOW
AREA	HILL AVE	ROAD_SURFACE	ASPHALT-CONC.
PIPE_TYPE	RCP	MH_REPORT	NONE

Comments MINOR MINERAL

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #03, THIS IS WITH THE FLOW
4	TAP TO THE LEFT		10 O/C	
17.6	TAP TO THE TOP		12 O/C	
29.7	WATER	1-2"	BOTTOM OF PIPE	
64.1	TAP TO THE LEFT		10 O/C	
111	SAG	MANY OF THEM		MINOR
135.9	TAP TO THE TOP		12 O/C	
155.6	INFILTRATION AT JOINT	LIGHT		
164	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
180.1	TAP TO THE LEFT		10 O/C	
216.4	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
236.5	MINERAL AT JOINT	LIGHT	BOTTOM OF PIPE	
264				CENTER OF MH-03A306A