Site ID	Location Description	TYPE	Actual Cost	Estimated Cost	CONTACT	City	Lat	Long
AM001	Lackson Rd & Middle River Rd	Shoulder washout 5 Loads	Alottudi Goot	Louinatoa ooot	Town of Amnicon	Amnicon	46 <sub>T</sub> 33' 41.442" N	91 <sub>-</sub> 50' 49.944" W
AM002	Kellogg Rd	2 Loads Gravel (Hole)			Town of Amnicon	Amnicon	46T 36' 33.696" N	91 <sub>T</sub> 54' 32.866" W
AM003	Moonshine Rd	1 Load Gravel (Hole)			Town of Amnicon	Amnicon	46 <sub>T</sub> 37' 6.017" N	91 <sub>T</sub> 50' 52.593" W
AM004	Moonshine Rd	3-4 loads for Driveways washing into rd			Town of Amnicon	Amnicon	46 <sub>T</sub> 37' 7.775" N	91 <sub>T</sub> 49' 50.775" W
AM005 CL001	Bayfield Rd Rudolph Rd	Scouring 2 Loads washout	\$1000		Town of Amnicon Cloverland	Amnicon Cloverland	46 <sub>T</sub> 35' 28.515" N 46 <sub>T</sub> 42' 21.260" N	91 <sub>T</sub> 50' 13.160" W 91 <sub>T</sub> 41' 25.939" W
CL001 CL002	Rudolph Rd	scouring fill	\$1000		Cloverland	Cloverland	46 <sub>T</sub> 42' 21.864" N	91 <sub>T</sub> 41 25.939 W 91 <sub>T</sub> 42' 54.381" W
CL002	Popple Bend Rd	scouring fill	\$1000		Cloverland	Cloverland	46 <sub>T</sub> 40' 41.755" N	91 <sub>T</sub> 43' 14.472" W
CL004	McNeils Landing Rd	scouring fill	\$1000		Cloverland	Cloverland	46 <sub>T</sub> 42' 19.364" N	91 <sub>T</sub> 36' 18.124" W
CL006	Town Park Rd	scouring	\$1000		Cloverland	Cloverland	46 <sub>T</sub> 40' 32.186" N	91 <sub>T</sub> 35' 46.422" W
DA001	Town TT from 35 to Swedish	Minor Washout	\$2842.80		Town of Dairyland	Dairyland	46 <sub>T</sub> 12' 55.430" N	92 <sub>T</sub> 10' 20.391" W
DA002	N Fire Lane-Town Rd TT to Hwy T	Several Washouts	\$378150		Town of Dairyland	Dairyland	46 <sub>T</sub> 10' 58.007" N	92 <sub>T</sub> 17' 35.830" W
DA003	Engine Hill off 35 to Lundquist	Several Washouts	\$3106.50		Town of Dairyland	Dairyland	46 <sub>T</sub> 14' 39.345" N	92 <sub>T</sub> 8' 30.848" W
DA004 DA005	Hughes Rd Kingsdale Rd West of Swedish	Minor Washouts Minor Washout	\$785.51 \$736.18		Town of Dairyland Town of Dairyland	Dairyland Dairyland	46 <sub>T</sub> 12' 47.520" N 46 <sub>T</sub> 14' 39.700" N	92 <sub>T</sub> 8' 5.591" W 92 <sub>T</sub> 16' 11.437" W
DA005 DA006	Cummings Rd off Kingdale to deadend	Minor Washout	\$540.89		Town of Dairyland	Dairyland	46T 14 59.700 N 46T 14' 52.546" N	92 <sub>T</sub> 16 11.437 W 92 <sub>T</sub> 14' 16.354" W
DA007	Swenson Rd off Kingsdale to deadend	Minor Washout	\$630.53		Town of Dairyland	Dairyland	46 <sub>T</sub> 14' 19.705" N	92 <sub>T</sub> 14' 18.270" W
DA008	Perkins off Kingsdale to deadend	Minor Washout	\$780.82		Town of Dairyland	Dairyland	46 <sub>T</sub> 15' 0.592" N	92 <sub>T</sub> 16' 46.165" W
DA009	Swedish Hwy from Kingsdale to Moose Rd	several washouts 2 culverts damaged/washout	\$2832.66		Town of Dairyland	Dairyland	46 <sub>T</sub> 16' 18.372" N	92 <sub>T</sub> 15' 30.121" W
DA010	Stuart Rd off Swedish to deadend	Minor Washouts	\$3400.81		Town of Dairyland	Dairyland	46 <sub>T</sub> 15' 57.393" N	92 <sub>T</sub> 15' 4.074" W
DA011	Moose Rd from Swedish to Hwy 35	several washouts 2 culverts damaged/washout	\$7608.72		Town of Dairyland	Dairyland	46 <sub>T</sub> 17' 16.185" N	92 <sub>T</sub> 12' 59.971" W
DA012	Summit Trail from Moose Rd to Townline	Minor washout	1151.14		Town of Dairyland	Dairyland	46T 19' 19.620" N	92 <sub>T</sub> 17' 33.690" W
DA013 DA014	Spruce Rd off Moose Rd to deadend Rocky Brook off Cty Rd T to County Line	Minor Washouts severe washouts 2 culverts damaged/washout	\$735.82 \$15047.21		Town of Dairyland Town of Dairyland	Dairyland Dairyland	46 <sub>T</sub> 16' 58.419" N 46 <sub>T</sub> 10' 45.103" N	92 <sub>T</sub> 13' 6.288" W 92 <sub>T</sub> 7' 47.612" W
DA014 DA015	Schoen Rd off Rocky Brook to deadend	several washouts	\$1860.59		Town of Dairyland	Dairyland	46 <sub>T</sub> 10' 8.652" N	92 <sub>T</sub> 7' 16.684" W
DA016	Big Beaver Rd off T to Park Rd	min damage of washouts.	\$735.82		Town of Dairyland	Dairyland	46 <sub>T</sub> 11' 42.290" N	92 <sub>T</sub> 5' 7.362" W
DA017	Park Rd off Rocky Brook to deadend	severe washouts	\$49.729.35		Town of Dairyland	Dairyland	46 <sub>T</sub> 11' 9.942" N	92 <sub>T</sub> 5' 19.494" W
DA018	Town Rd F off Bear Tree Rd to Cty Rd T	several washouts	2308.79		Town of Dairyland	Dairyland	46 <sub>T</sub> 11' 1.721" N	92 <sub>T</sub> 4' 34.308" W
DA019	Bear Tree Rd off Town Rd F to Hanson Rd1	several washouts	\$1238.73		Town of Dairyland	Dairyland	46 <sub>T</sub> 10' 25.908" N	92 <sub>T</sub> 6' 9.682" W
DA020	Dry Landing Rd off Town Rd F to deadend	min damage of washouts.	\$1034.06		Town of Dairyland	Dairyland	46° 9' 25.848" N	92° 6' 47.754" W
DA021	St Croix Dr	min damage of washouts.	\$1770.95		Town of Dairyland	Dairyland	46 <sub>T</sub> 12' 9.652" N	92 <sub>T</sub> 2' 49.060" W
DA022 DA023	School Rd off Hwy 35 to deadend	several washouts severe washouts	\$2085.56		Town of Dairyland	Dairyland	46 <sub>T</sub> 9' 53.388" N	92 <sub>T</sub> 13' 26.326" W
GO001	Andrews Rd off State Line Rd to deadend Flowage Ln	Scouring 4 Loads	\$3483.26		Town of Dairyland Town of Gordon	Dairyland Gordon	46 <sub>T</sub> 10' 58.015" N 46 <sub>T</sub> 15' 57.200" N	92 <sub>T</sub> 16' 47.371" W 91 <sub>T</sub> 53' 4.775" W
GO001 GO002	Denver Rd	Wash at Blacktop/Ditch			Town of Gordon	Gordon	46 <sub>T</sub> 14' 40.342" N	91 <sub>T</sub> 34' 11.143" W
GO003	Wilderness Dr	Scouring			Town of Gordon	Gordon	46 <sub>T</sub> 14' 59.304" N	91 <sub>T</sub> 36' 51.098" W
GO004	East Cabin Lane	Scouring/Pit Run Gravel			Town of Gordon	Gordon	46 <sub>T</sub> 18' 11.704" N	91 <sub>-</sub> 37' 35.586" W
GO005	Doetch Lane	Scouring 5 Gravel 4 Pit Run			Town of Gordon	Gordon	46 17' 15.481" N	91 <sub>T</sub> 39' 54.932" W
GO006	Bayfield Rd	Scouring			Town of Gordon	Gordon	46 <sub>T</sub> 19' 5.200" N	91 <sub>-</sub> 40' 16.428" W
GO007	Flat Lake Rd	Scouring 9 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 17' 39.961" N	91 <sub>T</sub> 44' 13.792" W
GO008	Town Line Rd	Scouring 10 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 19' 50.474" N	91 <sub>T</sub> 42' 39.975" W
GO009 GO010	Lidberg Bridge Rd	2 Loads			Town of Gordon	Gordon Gordon	46 <sub>T</sub> 15' 11.032" N 46 <sub>T</sub> 18' 8.291" N	91 <sub>T</sub> 41' 44.200" W
G0010 G0011	Simms Lake Rd Pine Cone Dr	Scouring 12 Loads 2 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 18' 8.291" N 46 <sub>T</sub> 15' 57.359" N	91 <sub>T</sub> 40' 47.852" W 91 <sub>T</sub> 42' 13.666" W
GO011	Simms Lake Rd & Swenson Ln	Grader Work			Town of Gordon	Gordon	46 <sub>T</sub> 17' 13.854" N	91 <sub>T</sub> 40' 35.109" W
GO013	Crestview Ln	1 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 16' 22.657" N	91 <sub>T</sub> 42' 24.689" W
GO014	Crestview Ln	3 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 16' 22.824" N	91 <sub>T</sub> 44' 1.687" W
GO015	Germann Rd	Scouring			Town of Gordon	Gordon	46 <sub>T</sub> 18' 57.430" N	91 <sub>T</sub> 39' 47.046" W
GO016	Connors Meadow Rd From German Rd to Woods I				Town of Gordon	Gordon	46 <sub>T</sub> 18' 18.627" N	91 <sub>T</sub> 38' 2.750" W
GO017	Town Line Rd	Scouring 18 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 19' 51.290" N	91 <sub>T</sub> 38' 53.607" W
GO018 GO019	Crestview Ln Fast Mail Rd	Scouring 7 Loads Crushed			Town of Gordon Town of Gordon	Gordon Gordon	46 <sub>T</sub> 16' 25.134" N 46 <sub>T</sub> 15' 41.209" N	91 <sub>T</sub> 45' 56.598" W 91 <sub>T</sub> 34' 19.952" W
GO019 GO020	East Cabin Lane	Grader Work			Town of Gordon	Gordon	46 <sub>T</sub> 18' 11.909" N	91 <sub>T</sub> 34 19.952 W 91 <sub>T</sub> 33' 44.389" W
G0020 G0021	Schaefer Rd	Grader Work			Town of Gordon	Gordon	46 <sub>T</sub> 17' 48.667" N	91 <sub>T</sub> 35' 32.706" W
GO021	Doetch Ln	Grader Work			Town of Gordon	Gordon	46 <sub>T</sub> 17' 15.625" N	91 <sub>T</sub> 35' 14.362" W
GO023	Doetch Ln	Grader Work			Town of Gordon	Gordon	46 <sub>T</sub> 17' 13.316" N	91 <sub>T</sub> 36' 48.928" W
GO024	Sand Rd	Grader Work			Town of Gordon	Gordon	46 <sub>T</sub> 18' 56.252" N	91 <sub>T</sub> 37' 32.259" W
GO025	Country Cir	Scouring 3 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 15' 18.740" N	91 <sub>T</sub> 46' 7.280" W
GO026	Williams Dr	Scouring 4 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 14' 45.377" N	91 <sub>T</sub> 46' 51.214" W
GO027 GO028	Bird Sanctuary Rd Burma Rd	Scouring 6 Loads			Town of Gordon Town of Gordon	Gordon	46 <sub>T</sub> 18' 6.885" N	91 <sub>T</sub> 49' 13.510" W
GO028 GO029	Ross Rd	Scouring 8 Loads Scouring 2 Loads			Town of Gordon	Gordon Gordon	46 <sub>T</sub> 17' 49.035" N 46 <sub>T</sub> 18' 23.734" N	91 <sub>T</sub> 54' 21.973" W 91 <sub>T</sub> 56' 8.916" W
GO030	Crotte Brook Rd	Scouring 3 Loads			Town of Gordon	Gordon	46 <sub>T</sub> 15' 30.173" N	91 <sub>T</sub> 58' 25.978" W
HI001	Catherine Lake Rd	culvert washout			Highland	Highland	46 <sub>T</sub> 20' 39.346" N	91 <sub>T</sub> 33' 42.703" W
HI002	Beauregard Lake Rd	culvert washout			Highland	Highland	46T 19' 51.395" N	91 <sub>T</sub> 34' 48.633" W
HI003	Beauregard Lake Rd	culvert washout			Highland	Highland	46 <sub>T</sub> 19' 51.799" N	91 <sub>-</sub>
HI004	Rocky Lake Rd	culvert washout			Highland	Highland	46 <sub>T</sub> 20' 39.922" N	91 <sub>T</sub> 36' 40.177" W
HI005	Sutfin Rd	washout			Highland	Highland	46 <sub>T</sub> 20' 43.040" N	91 <sub>T</sub> 37' 12.255" W
HI006	Commisky Rd	washout			Highland	Highland	46 <sub>T</sub> 20' 23.182" N	91 <sub>T</sub> 38' 5.119" W
HI007 HI008	Commisky Rd Sutfin Rd	washout washout			Highland Highland	Highland Highland	46 <sub>T</sub> 20' 15.019" N 46 <sub>T</sub> 20' 41.858" N	91 <sub>T</sub> 38' 4.729" W 91 <sub>T</sub> 38' 49.568" W
HI009	Sutfin Rd	washout			Highland	Highland	46 <sub>T</sub> 20' 41.922" N	91 <sub>T</sub> 30 49.506 W 91 <sub>T</sub> 39' 17.137" W
HI010	Commisky Rd	Culvert			Highland	Highland	46 <sub>T</sub> 21' 2.043" N	91 <sub>T</sub> 38' 5.460" W
HI011	Commisky Rd	washout			Highland	Highland	46 <sub>T</sub> 20' 51.186" N	91 <sub>T</sub> 38' 5.624" W
HI012	County Line Rd	washout			Highland	Highland	46 <sub>T</sub> 22' 17.011" N	91 <sub>T</sub> 33' 5.567" W
HI013	Loon Lake Rd	washout			Highland	Highland	46 <sub>T</sub> 22' 40.988" N	91 <sub>T</sub> 33' 27.182" W
HI014	Loon Lake Rd	washout			Highland	Highland	46 <sub>T</sub> 22' 59.739" N	91 <sub>T</sub> 34' 0.083" W
HI015	Sandmon Rd	washout			Highland	Highland	46 <sub>T</sub> 24' 1.223" N	91 <sub>T</sub> 40' 31.544" W
HI016	Forestry Rd	washout			Highland	Highland	46 <sub>T</sub> 29' 40.109" N	91 <sub>T</sub> 38' 25.937" W

HI017	Forestry Rd	washout			Highland	Highland	46 <sub>T</sub> 28' 30.643" N	91-	38' 42.659" W
HI018	CCC Rd	washout			Highland	Highland	46 <sub>T</sub> 28' 37.557" N	91 <sub>T</sub>	36' 49.810" W
HI019	CCC Rd	washout			Highland	Highland	46T 29' 34.862" N	91 <sub>T</sub>	36' 49.005" W
HI020	Volker Rd	washout			Highland	Highland	46 <sub>T</sub> 28' 57.293" N	91 <sub>T</sub>	34' 22.341" W
HI021	Volker Rd	washout			Highland	Highland	46 <sub>T</sub> 27' 53.339" N	91 <sub>T</sub>	34' 22.446" W
HI022 HI023	Minnesuing Rd	Culvert			Highland	Highland	46 <sub>T</sub> 28' 26.801" N	91 <sub>T</sub>	41' 16.366" W
HI023 HI024	Schaller Short Cut Rd Highland Cemetery	washout trees down			Highland Highland	Highland Highland	46 <sub>T</sub> 26' 25.175" N 46 <sub>T</sub> 25' 0.618" N	91T	40' 29.705" W 38' 43.944" W
LA001	Pine Central Rd	Debris	\$600	600	Lakeside	Lakeside	46 <sub>T</sub> 38' 6.875" N		45' 47.400" W
LA002	Bardon Creek Rd	Scouring	\$725	000	Lakeside	Lakeside	46+ 37' 38.451" N		47' 2.419" W
LA003	Moonshine Rd	Scouring	\$725		Lakeside	Lakeside	46 <sub>T</sub> 37' 9.170" N	91-	47' 54.107" W
LA004	Halkett Rd	Scouring	\$725		Lakeside	Lakeside	46 <sub>T</sub> 41' 11.822" N	91 <sub>T</sub>	47' 26.723" W
LA005	Middle River Rd	Scouring			Lakeside	Lakeside	46 <sub>T</sub> 41' 20.630" N		49' 46.861" W
LA006	American River Rd	Debris	\$300	300	Lakeside	Lakeside	46 <sub>T</sub> 39' 4.859" N	91 <sub>T</sub>	50' 46.343" W
LA007 LA008	22 Rd	Scouring	\$725	300	Lakeside Lakeside	Lakeside	46 <sub>T</sub> 38' 59.349" N 46 <sub>T</sub> 38' 19.555" N	91 <sub>T</sub>	51' 24.025" W 50' 46.019" W
LA008 LA009	Anderson Rd Sage Rd	Debris Debris/Scouring	\$300	300	Lakeside Lakeside	Lakeside Lakeside	46 <sub>T</sub> 41' 19.763" N	91T	51' 0.511" W
LA010	Beach Rd	Scouring			Lakeside	Lakeside	46 <sub>T</sub> 41' 22.955" N	91-	51' 25.770" W
LA011	Old Hwy 13	Culvert 2 - 48"	\$19000	\$19000	Lakeside	Lakeside	46 <sub>T</sub> 38' 51.225" N		53' 5.387" W
LA012	Pukema Rd	Debris			Lakeside	Lakeside	46° 39' 28.818" N	91° 5	3' 52.665" W
LA013	River Rd W	Scouring	\$725		Lakeside	Lakeside	46 <sub>T</sub> 39' 28.042" N		53' 58.413" W
MA001	Wouri Rd & Lindgren Rd South	Washout	\$3382.28		Maple	Maple	46 <sub>T</sub> 36' 12.163" N	91 <sub>T</sub>	41' 58.796" W
MA002	Mason Rd		\$215.61		Maple	Maple	46 <sub>T</sub> 34' 44.177" N	91 <sub>T</sub>	40' 24.418" W
MA003 MA003A	Blueberry Rd Blueberry Rd		\$215.61 \$215.61		Maple Maple	Maple Maple	46 <sub>T</sub> 34' 30.739" N 46 <sub>T</sub> 34' 30.560" N	91T	41' 0.832" W 40' 25.306" W
MA004	Bardon Creek Rd		\$862.44		Maple	Maple	46 <sub>T</sub> 37' 34.123" N	91—	44' 14.602" W
MA005	Lund Rd		\$862.44		Maple	Maple	46 <sub>T</sub> 37' 59.269" N		43' 46.906" W
MA006	Karna Rd & Haukkala Rd		\$215.61		Maple	Maple	46 <sub>T</sub> 37' 33.473" N	91 <sub>T</sub>	41' 21.734" W
MA007	Williams Rd		\$862.44		Maple	Maple	46 <sub>T</sub> 38' 6.324" N	91 <sub>T</sub>	41' 9.758" W
MA008	Hendrickson Rd		\$168.32		Maple	Maple	46 <sub>T</sub> 36' 40.597" N		41' 56.881" W
MA009	Dump Rd		\$44.83		Maple	Maple	46 <sub>T</sub> 34' 56.251" N		41' 59.317" W
MA010	Lindgren Rd	Washout	\$3051.20		Maple	Maple	46 <sub>T</sub> 36' 14.499" N	91 <sub>T</sub>	41' 41.719" W
MA011 MA012	Colby Rd Estness Rd		\$215.61 \$215.61		Maple	Maple	46 <sub>T</sub> 38' 44.107" N 46 <sub>T</sub> 34' 4.507" N	91 <sub>T</sub>	40' 43.620" W 42' 41.266" W
MA012 MA013	Hendrickson Rd		\$215.61 \$215.61		Maple Maple	Maple Maple	46 <sub>T</sub> 36' 40.553" N		42' 9.786" W
MA014	Niemi Rd		\$215.61		Maple	Maple	46+ 37' 21.100" N	91 <del>-</del>	41' 39.706" W
SS001	Waterbury Rd	Scouring Wash out	Ψ210.01		Town of Solon Springs	Solon Springs	46 <sub>T</sub> 19' 10.079" N	91 <del>-</del>	54' 54.269" W
SS002	Copeland Rd	Scouring Wash out			Town of Solon Springs	Solon Springs	46 <sub>T</sub> 19' 23.827" N	91 <del>-</del>	53' 0.474" W
SS003	Ramal Rd	Scouring Wash out			Town of Solon Springs	Solon Springs	46 <sub>T</sub> 19' 53.842" N	91 <sub>T</sub>	52' 8.066" W
SU001	Patzau Foxboro RD Little Balsam Creek	Culvert Damage			Town of Summit	Summit	46 <sub>T</sub> 29' 24.187" N		13' 24.547" W
SU002	Dietz Road	Washed out both lanes	\$500		Town of Summit	Summit	46 <sub>T</sub> 24' 23.150" N		11' 44.906" W
SU003	Patzau Foxboro RD	Missing part of lane	****		Town of Summit	Summit	46 <sub>T</sub> 29' 24.216" N		15' 50.703" W
SU004 SU005	Zuchowski RD Patzau Foxboro RD	Culvert washout Culvert Damage	\$300 \$8500		Town of Summit Town of Summit	Summit Summit	46 <sub>T</sub> 30' 39.684" N 46 <sub>T</sub> 29' 23.841" N		13' 20.767" W 15' 26.772" W
SU005 SU006	Severson Rd	Culvert Damage Culvert Damage	φοσου		Town of Summit	Summit	46 <sub>T</sub> 29 23.041 N 46 <sub>T</sub> 29' 43.078" N		13' 29.653" W
SU007	Pioneer Trail	High water road closed & Trees down			Town of Summit	Summit	46 <sub>+</sub> 25' 4.001" N		7' 10.072" W
SU008	Michesky Rd	Trees down along the road & Washout	\$500		Town of Summit	Summit	46 <sub>T</sub> 28' 32.284" N	92 <sub>T</sub>	4' 49.307" W
SU009	Finn Point Rd	Trees down			Town of Summit	Summit	46 <sub>T</sub> 28' 36.503" N	92 <sub>T</sub>	3' 8.977" W
SU010	Mud Lake Rd	Trees down			Town of Summit	Summit	46 <sub>T</sub> 28' 12.586" N		4' 58.532" W
SU011	Bear Laker Rd	Trees down			Town of Summit	Summit	46 <sub>T</sub> 23' 34.200" N		5' 39.460" W
SU012 SU013	Tower Fire Rd Fall Rd	Trees down Washed Out	\$800		Town of Summit Town of Summit	Summit Summit	46 <sub>T</sub> 22' 28.037" N 46 <sub>T</sub> 20' 56.089" N		5' 5.402" W 9' 10.935" W
SU013 SU014	Nindorf Rd	Washed Out	\$1000 \$1000		Town of Summit	Summit	46 <sub>T</sub> 30' 0.161" N		17' 13.947" W
SU014	Patzau Foxboro Rd	Washed Out	ψ1000		Town of Summit	Summit	46 <sub>T</sub> 29' 24.115" N		17' 12.102" W
SU015	Patzau Foxboro Rd	Washed Out			Town of Summit	Summit	46 <sub>T</sub> 29' 23.846" N		16' 38.245" W
SU016	Pelkey RD	Trees Down			Town of Summit	Summit	46 <sub>T</sub> 29' 58.901" N	92T	15' 31.907" W
SU016	Drolson RD	Trees Down & Washout	\$1500		Town of Summit	Summit	46 <sub>T</sub> 29' 6.479" N		15' 31.032" W
SU017	Little Balsam Rd & Moen RD	Washout	\$2000		Town of Summit	Summit	46 <sub>T</sub> 28' 55.762" N	92 <sub>T</sub>	14' 15.074" W
SU018	Moen RD	Washout	0000		Town of Summit	Summit	46 <sub>T</sub> 29' 8.965" N		14' 14.060" W
SU019 SU020	Ekelund RD Vana RD	Washout Washout	\$800 \$500		Town of Summit Town of Summit	Summit Summit	46 <sub>T</sub> 29' 27.819" N 46 <sub>T</sub> 29' 27.290" N		14' 15.263" W 13' 18.456" W
SU020 SU021	Caragan RD	Washout	\$800		Town of Summit	Summit	46 <sub>T</sub> 29 27.290 N 46 <sub>T</sub> 29' 20.568" N		13' 22.879" W
SU022	Big Balsam RD	Washout	φοσο		Town of Summit	Summit	46 <sub>T</sub> 27' 40.106" N		14' 14.164" W
SU023	Breitzmann Lake RD	Washout	\$1000		Town of Summit	Summit	46 <sub>T</sub> 28' 19.908" N	92 <sub>T</sub>	13' 0.158" W
SU024	Breitzmann Lake RD	Trees Down			Town of Summit	Summit	46 <sub>T</sub> 27' 30.864" N	92 <sub>T</sub>	13' 5.346" W
SU025	Big Balsam RD	Washout	\$2000		Town of Summit	Summit	46 <sub>T</sub> 26' 19.927" N		15' 31.160" W
SU026	Big Balsam RD	Washout			Town of Summit	Summit	46 <sub>T</sub> 25' 59.182" N		15' 31.576" W
SU027	Breitzmann Lake RD	Trees Down			Town of Summit	Summit	46 <sub>T</sub> 25' 42.300" N		12' 44.021" W
SU028 SU029	Foxboro Chaffey RD	Washout Washout	\$2000		Town of Summit Town of Summit	Summit Summit	46 <sub>T</sub> 27' 3.068" N 46 <sub>T</sub> 25' 6.299" N		16' 46.186" W 11' 21.480" W
SU029 SU030	Foxboro Chaffey RD Summit Tr	vvasnout Trees Down			Town of Summit Town of Summit	Summit	46 <sub>T</sub> 25 6.299 N 46 <sub>T</sub> 23' 45.641" N	1 222	12' 8.139" W
SU030 SU031	Summit Tr	Washout			Town of Summit	Summit	46 <sub>+</sub> 23' 22.299" N		12' 22.381" W
SU031	Summit Tr	Washed Out			Town of Summit	Summit	46 <sub>T</sub> 22' 45.636" N		12' 18.225" W
SU033	Summit Tr	Washed Out & Trees Down	\$2500		Town of Summit	Summit	46 <sub>T</sub> 22' 25.919" N		15' 28.268" W
SUP001	Hilpiper Rd	Washed out			2905 Town of Superior	Town of Superior	46 <sub>T</sub> 33' 2.522" N	92 <sub>T</sub>	14' 46.600" W
SUP002	Barnes Rd	Culvert washed out road impassable			23587 Town of Superior	Town of Superior	46 <sub>T</sub> 33' 2.522" N	92 <sub>T</sub>	14' 46.600" W
SUP003	Dedham Rd	South side of bridge approach washed out			645 Town of Superior	Town of Superior	46 <sub>T</sub> 33' 2.522" N		14' 46.600" W
SUP004 VOS001	S Finn Rd	Scouring	\$9100		281 Town of Superior	Town of Superior	46 <sub>T</sub> 33' 2.522" N		14' 46.600" W
VOS001 VOS002	Cemetery Rd Cemetery Rd	36" Culvert washed out Culvert washed out	\$9100 \$2900		Village of Superior Village of Superior	Village of Superior	46 <sub>T</sub> 39' 24.019" N 46 <sub>T</sub> 38' 57.743" N		7' 7.786" W 7' 7.188" W
V 0 3 0 0 2	Sometery Nu	Current washed out	ΨΣσΟΟ		village of Superior	village of Superior	-0T‰ 00 01.140 N	94 <b>⊤</b> ⊚	, , , 100 VV

WA001	crotte brook rd washed out east of bridge	washed out east of bridge		Town of Wascott	Wascott	46 <sub>T</sub> 13' 46.510" N	92 <sub>T</sub> 2' 49.392" W
WA002	crotte brook rd culvert washed out	culvert washed out		Town of Wascott	Wascott	46 <sub>T</sub> 14' 30.429" N	92 <sub>T</sub> 1' 7.010" W
WA003	Bass Lake Rd	culverts and road washed out		Town of Wascott	Wascott	46 <sub>T</sub> 13' 29.876" N	91 <sub>T</sub> 50' 33.150" W
WA004	Cemetery Rd	culverts		Town of Wascott	Wascott	46 <sub>T</sub> 11' 21.064" N	91 <sub>T</sub> 49' 10.903" W
WA005	Miles Lake Rd	culverts and road washed out		Town of Wascott	Wascott	46 <sub>T</sub> 9' 38.194" N	91 <sub>T</sub> 51' 40.089" W
WA006	North Cheever Bridge	road washed out		Town of Wascott	Wascott	46 <sub>T</sub> 10' 2.085" N	91 <sub>T</sub> 41' 42.253" W
WA007	Berger Rd	culvert washed out		Town of Wascott	Wascott	46 <sub>T</sub> 10' 23.715" N	91 <sub>T</sub> 40' 28.296" W
WA008	Cheever Rd culverts	culverts washed out		Town of Wascott	Wascott	46 <sub>T</sub> 10' 27.782" N	91 <sub>+</sub> 37' 50.389" W
WA009	North Cheever Bridge			Town of Wascott	Wascott	46 <sub>T</sub> 11' 41.232" N	91 <sub>T</sub> 38' 10.350" W
WA010	Coppermine Loop Rd	Bridge washed out on north/south ends		Town of Wascott	Wascott	46 <sub>T</sub> 13' 26.291" N	91 <sub>T</sub> 33' 50.987" W
WA011	Coppermine Loop Rd	South bridge washed out both sides of bridge		Town of Wascott	Wascott	46 <sub>T</sub> 12' 58.991" N	91 <sub>T</sub> 34' 31.911" W
WA012	Coppermine Loop Rd	60" culvert washed out		Town of Wascott	Wascott	46 <sub>T</sub> 13' 14.855" N	91 <sub>T</sub> 33' 34.870" W
WA013	Coppermine Loop Rd	washed out on both sides of culvert		Town of Wascott	Wascott	46 <sub>T</sub> 13' 11.206" N	91 <sub>T</sub> 33' 37.499" W
WA014	East Coppermine Rd	1st set of culverts washed out		Town of Wascott	Wascott	46 <sub>T</sub> 12' 3.897" N	91 <sub>T</sub> 35' 49.849" W
WA015	East Coppermine Rd	2nd set of culverts washed out		Town of Wascott	Wascott	46 <sub>T</sub> 12' 18.840" N	91 <sub>T</sub> 35' 25.475" W
WA016	Carps Creek Rd	culvert washed out		Town of Wascott	Wascott	46 <sub>T</sub> 13' 31.329" N	91 <sub>T</sub> 57' 57.680" W
XDCFor001	Fowlers Circle - Mooney Dam Park	200 yard washout stabilize shore	\$7500	DC Forestry	Gordon	46 <sub>T</sub> 15' 31.096" N	91 <sub>T</sub> 34' 14.771" W
XDCFor002	Lucius Woods County Park	Gravel washout shouldering	\$500	DC Forestry	Solon Springs	46 <sub>T</sub> 21' 2.544" N	91 <sub>T</sub> 48' 55.843" W
XDCFor003	Gordon Dam - near launch	Corrosion/few campsites impacted	\$3000	DC Forestry	Gordon	46 <sub>T</sub> 15' 12.985" N	91 <sub>T</sub> 55' 40.034" W
XDCFor004	Hunters Trail	Washout		DC Forestry	Gordon	46 <sub>T</sub> 24' 11.767" N	92 <sub>T</sub> 2' 26.705" W
XDCHWY001	CTH W	Debris removal CTH W br @ Nemadji R & Rd Repair	\$55000	DC Hwy	Summit	46 <sub>T</sub> 33' 2.522" N	92 <sub>T</sub> 14' 46.600" W
XDCHWY002	CTH BB	Repair shoulder washouts along CTH BB	\$6000	DC Hwy	Summit	46 <sub>T</sub> 29' 23.524" N	92 <sub>T</sub> 11' 57.199" W
XXWI006	Wild Rivers State Trail	Sink-hole in trail caused by separated culvert sec	\$5000	WIDNR	Parkland	46°16'24.54"N	91°48'1.77"W
XXWI005	Wild Rivers State Trail	Rilling across trail, 25x25 foot area, 1 ft depth	\$500	WIDNR	Gordon	46°34'51.18"N	91°57'43.99"W
XXWI007	Saunders State Trail	Sink-hole in trail caused by separated culvert sec	\$150000	WIDNR	Town of Superior	46°35'32.05"N	92°13'49.81"W
XXWI008	Saunders State Trail	Channel undercutting abutment fill causing riprap	\$15000	WIDNR	Town of Superior	46°35'1.64"N	92°15'35.45"W
XXWI000	Saunders State Trail	Fill behind bridge abutment undermining abutment w	\$15000	WIDNR	Town of Superior	46°34'42.72"N	92°16'28.15"W
XXWI010			\$500	WIDNR	Town of Superior	46°34'29.08"N	92°17'2.92"W
	Saunders State Trail	Fill deposited on the trail					
XXWI011	Saunders State Trail	75+ foot hillside slumping approximatly 1-ft verti	\$250000	WIDNR	Town of Superior	46°34'17.66"N	92°17'13.19"W