

Viking Pipe Services
Number: MH-060003 to MH-060002

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	7/28/99	PIPE SIZE	15" X 4'
TIME	12:46:30 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	WEST CENTER OF TRAIN YARD	LOCATION	ACROSS TRAIN YARD SOUTHSIDE OF BRIDGE
DWN_DESCRIPTOR	CENTER OF TRAIN YARD	LENGTH/RUN	376'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	EAST
TAPE_#	#6-99 SUPERIOR-MW	FLOW_RATE	LOW
COUNTER	01:05:44	DIR_MEASURED	WITH FLOW
SETUP_#	#07	ROAD_SURFACE	GRAVEL
AREA	#06	MH_REPORT	NONE
PIPE_TYPE	RCP		

Comments LIGHT DIRT/DEBRI W/ROOTS

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #07, THIS IS WITH THE FLOW.
178.2	DIRT/DEBRI	1-2"	BOTTOM OF PIPE	
190.4				SEPERATED JOINT THAT'S BEEN PATCHED
239	ROOTS AT JOINT	LIGHT		
341.3	DEBRI	SMALL	BOTTOM OF PIPE	
376				CENTER OF MH-060002