

**Viking Pipe Services**  
**Number: MH-060005 to MH-060004**

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	7/28/99	PIPE SIZE	15" X 4'
TIME	11:48:02 AM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPT	BETWEEN	LOCATION	RUNS ALONG
	WASHINGTON/ELMIRA		NORTHSIDE OF
DWN_DESCRIPT	EAST OF ELMIRA		FRONTAGE RD.
JOB_#	17-99	LENGTH/RUN	307'
CLIENT	SUPERIOR,WISC.	INSPECTOR	MW
TAPE_#	#6-99 SUPERIOR-MW	FLOW_DIR	EAST
COUNTER	00:43:08	FLOW_RATE	LOW
SETUP_#	#05	DIR_MEASURED	WITH FLOW
AREA	#06	ROAD_SURFACE	GRASS
PIPE_TYPE	RCP	MH_REPORT	NONE

Comments            LIGHT DIRT/DEBRI W/ROOTS

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #05, THIS IS WITH THE FLOW.
10	DIRT/DEBRI	2-4"	BOTTOM OF PIPE	
100	MINERAL AT JOINT	LIGHT		
104.1	MINERAL AT JOINT	LIGHT		
113.8	DIRT/DEBRI	0-1"	BOTTOM OF PIPE	
177.8	MINERAL AT JOINT	LIGHT		
226	INFILTRATION AT JOINT	LIGHT	MANY OF THEM	
307				CENTER OF MH-060004