## Viking Pipe Services Number: MH-060006 to MH-060005

<u>FIELD</u> DATE TIME UP_DESCRIPT	<u>VALUE</u> 7/28/99 11:30:43 AM BETWEEN	FIELD PIPE SIZE JOINT_TYPE	VALUE 15" × 4' BELL SPIGOT
o52001 (II 1	GARFIELD/WASHINGTO N	LOCATION	RUNS ALONG SOUTHSIDE OF FRONTAGE RD.
DWN_DESCRIPT	BETWEEN WASHINGTON/ELMIRA	LENGTH/RUN INSPECTOR	374' MW
JOB_#	17-99	FLOW DIR	EAST
CLIENT	SUPERIOR, WISC.	FLOW_RATE	LOW
TAPE_#	#6-99 SUPERIOR-MW	DIR_MEASURED	WITH FLOW
COUNTER	00:33:43	ROAD_SURFACE	GRAVEL
SETUP_#	#04	MH_REPORT	NONE
AREA	#06	_	· · - · · -
PIPE_TYPE	RCP		

Comments

LIGHT DIRT/DEBRI W/ROOTS

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7	·			START OF RUN #04,THIS IS WITH THE FLOW.
98.7	CRACKED/BRO KEN JOINT			
180.5	DIRT/DEBRI	2-4"	BOTTOM OF PIPE	
374				CENTER OF MH-060005