Surveyors Name	Certificate Number	System Owner	Survey Cus	tomer		Orainage Area	Sheet		
/lickey Webster	T-605-2280	City of Superior		City of Supe	erior		District 01	1 of 1	
P/O No.	Pipe Segment Reference	Date Time	Location (Street	Name and Nun	nber)	Locality (City)	)		
	Water-ST010152	2007/10/04 10:07	Cummings Ave			Superior			
urther Location	Details		Upstrea	am Manhole Nu	mber	Rim to Invert	Grade to Invert	vert Rim to Grade	
			ST010 <sup>-</sup>	152					
Downstream Ma	nhole Number Rim to Invert	Grade to Invert Rim to	Grade Use	of Sewer	Direction	Flo	w Control	Height	
<i>N</i> ater			Storn	nwater	Downstr	eam		36 in.	
	na Matarial	Ln. Method	Joint Length Tot	al Length	Length Surveyed	Year Laid	Year Rehab.	Tape/Media No.	
Vidth Shap	oe Material	Lii. Metiloa							
Vidth Shap		Lii. Ivietilou	89.2 ft. 89.		89.2 ft.			376	
				2 ft.		dditional Informa	tion	376	

Distance (Feet)	Video Ref.	Group	Description	Modifier	Cont. Defect	inches 1st	Inches 2nd	%	Joint	At/ From	То	Image Ref.	Remarks
0.00		Access Point	Manhole										ST010152
0.00		Miscellaneous	Water Level					5					
44.40		Line	Right										
89.20		Miscellaneous	Survey Abandoned										Debris in Line
89.20		Access Point	Manhole		1								Debris in Line