

**Viking Pipe Services**  
**Number: MH-050316A to MH-050316**

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	6/4/99	PIPE SIZE	15" X 4'
TIME	10:21:59 AM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	KIRK ROLSON ST.	LOCATION	ALONG WESTSIDE OF HILL AVE.
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE.	LENGTH/RUN	225'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	NORTH
TAPE_#	#1 SUPERIOR-MW-99	FLOW_RATE	MEDIUM
COUNTER	01:45:37	DIR_MEASURED	WITH FLOW
SETUP_#	#04	ROAD_SURFACE	ASPHALT-CONC.
AREA	HILL AVE	MH_REPORT	SEE ATTACHED
PIPE_TYPE	RCP		

Comments            MINERAL ON COUPLE OF JOINTS

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0	WATER	2-4"	BOTTOM OF PIPE	START OF RUN #04, THIS IS WITH THE FLOW.
53	MINERAL AT JOINT	LIGHT		
225				CENTER OF MH-050316