

**Viking Pipe Services**  
**Number: MH-03A306A to MH-03A306**

<b>FIELD</b>	<b>VALUE</b>	<b>FIELD</b>	<b>VALUE</b>
DATE	6/7/99	PIPE SIZE	15" X 4'
TIME	2:00:02 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	NO. 24TH ST.	LOCATION	RUNS ALONG
DWN_DESCRIPTOR	WESTSIDE OF HILL AVE		WESTSIDE OF HILL AVE
JOB_#	17-99	LENGTH/RUN	137'
CLIENT	SUPERIOR WISC.	INSPECTOR	MW
TAPE_#	#3 SUPERIOR-MW-99	FLOW_DIR	NORTH
COUNTER	00:10:23	FLOW_RATE	LOW
SETUP_#	#04	DIR_MEASURED	WITH FLOW
AREA	HILL AVE	ROAD_SURFACE	ASPHALT-CONC.
PIPE_TYPE	RCP	MH_REPORT	NONE

Comments            MINOR MINERAL

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #04. THIS IS WITH THE FLOW
5.2	INFILTRATION AT JOINT	LIGHT		
16.9	INFILTRATION AT JOINT	LIGHT		
94.2	MINERAL AT JOINT	LIGHT		
137				CENTER OF MH-03A306