



Stack Bros.
3119 Hill Ave. Superior WI

Tel: 7153982964
Fax:
E-mail:

Inspection Report

MH3A308A-MH3A0309

Date 6/12/2018	P/O. No.	Weather Dry	Surveyor's Name Josh Gordon	Pipe Segment Reference MH050310-MH3A0309	Section No. 3
Certificate No. U-215-06023623	Survey Customer	System Owner	Preset :	Pre-Cleaning No Pre-Cleaning	Sewer Category

Street N of INT of Hill & 28th	Use of Sewer Sanitary	Upstream MH MH050310 MH3A0309
City City of Superior	Drainage Area District 3A	Downstream MH MH3A0309 MH3A308A
Loc. details Light Highway	Flow Control	Dir. of Survey Upstream
Location Code	Length surveyed 105.61 ft	Section Length 105.61 ft

Purpose of Survey Routine Assessment	Joint Length
Year Laid	15 inch
Year Rehabilitated 4000	Material Reinforced Concrete Pipe
Tape / Media No. 952	Lining Method

Add. Information :

1:266	Position	Code	Observation	Photo	Grade
	0.00	AMH	Manhole, MH3A0309 / MH3A0309 MH3A308A		
	0.00	MWL	Water Level, 40 % of cross sectional area		
	75.20	MWLS	Water Level, Sag in pipe, 20 % of cross sectional area		
	105.58	SSS	Surface Spalling, from 7 o'clock, to 5 o'clock		
	105.61	OBR	Obstacles Rocks, 15 % of cross sectional area, at 6 o'clock		
	105.61	MSA	Survey Abandoned, rocks in pipe; tipping camera / rocks in pipe; tipping camera		

QSR	QMR	SPR	MPR	OPR	SPRI	MPRI	OPRI
-----	-----	-----	-----	-----	------	------	------