Pipe Televising Report

179

Televised by: Viking Pipe Service
Date Televised: 10-13-97 Tape #: 2 S: 1:46:57 E: 1:47:16
Time Starting ___:____ AM/PM Time Finished ___:____ AM/PM
Weather Condition
Precipitation: [✓] None [] Light [] Heavy Temperature: 35 °F.
Conditions: [✓] Clear [] Partly Cloudy [] Cloudy [] Stormy
Line #: 050034-050034A Length: _____'
From Manhole #: MH-050034 to Manhole #: MH-050034A
Pipe Size: 8 " Pipe Material: [] PVC [✓] VCP [] RCP [] Other: _____
Direction of televising: [✓] Upstream [] Downstream
_____' Pipe Sections Flow: [] None [✓] Low [] ½ pipe [] ¾ pipe

Footage	Observations
0	@ MH 050034
3	pipe size change from 8" VCP to 6" VCP.