

Viking Pipe Services
Number: MH-060001 to MH-060002

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	7/28/99	PIPE SIZE	15" X 4'
TIME	1:42:58 PM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	CENTER OF TRAIN	LOCATION	ACROSS TRAIN YARD
	YARD		SOUTHSIDE OF
DWN_DESCRIPTOR	CENTER OF TRAIN		BRIDGE
	YARD	LENGTH/RUN	377'
JOB_#	17-99	INSPECTOR	MW
CLIENT	SUPERIOR,WISC.	FLOW_DIR	EAST
TAPE_#	#6-99 SUPERIOR-MW	FLOW_RATE	LOW
COUNTER	01:23:30	DIR_MEASURED	AGAINST FLOW
SETUP_#	#09	ROAD_SURFACE	GRASS-DIRT
AREA	#06	MH_REPORT	NONE
PIPE_TYPE	RCP		

Comments FEW SAGS,LIGHT ROOTS

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
0				START OF RUN #09,THIS IS AGAINST THE FLOW.
4.8	ROOTS AT JOINT	LIGHT		
23.4	DIRT/DEBRI	0-1"	BOTTOM OF PIPE	
37.4	ROOTS AT JOINT	LIGHT		
40.6	ROOTS AT JOINT	LIGHT		
76	DIRT/DEBRI	1-2"	BOTTOM OF PIPE	
78.6	SEPERATED JOINT			AT CUT IN PATCH
192				FEW SAGS
310.8	ROOTS AT JOINT	LIGHT		
377				CENTER OF MH-060002