Pipe Televising Report

Televised by: Infratech
Date Televised: 12-16-98 Tape #: 3 1:36:39 1:44:07
Weather Condition
Precipitation: [X] None [] Light [] Heavy Temperature: 35 °F.
Conditions: [] Clear [X] Partly Cloudy [] Cloudy [] Stormy
Line #: 060004 - 060005 Length: 302 '
From Manhole #: 060004 to Manhole #: 060005
Pipe Size: 15 " Pipe Material: [] PVC [] VCP [X] RCP [] Other: _____
Direction of televising: [X] Upstream [] Downstream
Flow: [X] None [] Low [] ½ pipe [] ¾ pipe LS #3 shut off.

Footage	Observations
0 '	@ MH-060004 EAST OF ELMIRA & BERNARD ½
'	flow - ¼ pipe.
'	grease along sides
'	4" section of RCP pipe.
190 '	some debris rocks/gravel
240 '	heavier debris rock/gravel
265 '	¼ pipe of debris rock/gravel
302 '	@ MH-060005