Pipe Televising Report

Televised by: Infratech
Date Televised: 12-15-98 Tape #: 3 1:26:48
Weather Condition 1:36:42
Precipitation: [X] None [] Light [] Heavy Temperature: 30x°F.
Conditions: [] Clear [] Partly Cloudy [] Cloudy [] Stormy
Line #: 060007 - 060234 Length: 141 '
From Manhole #: 060234 to Manhole #: 060007
Pipe Size: 15 " Pipe Material: [] PVC [] VCP [X] RCP [] Other: _____
Direction of televising: [] Upstream [X] Downstream
Flow: [X] None [] Low [] ½ pipe [] ¾ pipe

Footage	Observations
0'	@ MH-060234
16'-28	gravel less than 1/4 pipe.
76'	gravel less than 1/4 pipe.
100'-141	light mineral deposit @ joints
130'	gravel more than 1/4 pipe to 1/3 pipe
141'	unable to proceed due to gravel 1/3 of pipe.