

**Viking Pipe Services**  
**Number: MH-060009 to MH-060008**

<u>FIELD</u>	<u>VALUE</u>	<u>FIELD</u>	<u>VALUE</u>
DATE	7/28/99	PIPE SIZE	15" X 3'
TIME	7:55:40 AM	JOINT_TYPE	BELL SPIGOT
UP_DESCRIPTOR	BETWEEN	LOCATION	ALLEYWAY BETWEEN
	MISSOURI/MARYLAND		BELKNAP/N. 16TH ST.
DWN_DESCRIPTOR	BETWEEN	LENGTH/RUN	335'
	MARYLAND/LOGAN	INSPECTOR	MW
JOB_#	17-99	FLOW_DIR	EAST
CLIENT	SUPERIOR,WISC.	FLOW_RATE	LOW
TAPE_#	#6-99 SUPERIOR-MW	DIR_MEASURED	WITH FLOW
COUNTER	00:00:00	ROAD_SURFACE	GRAVEL
SETUP_#	#01	MH_REPORT	NONE
AREA	#06		
PIPE_TYPE	RCP		

Comments            LIGHT DIRT/DEBRI W/ROOTS

FOOTAGE	DEFECT	RATING	CLOCK POSIT	COMMENTS
7				START OF RUN #01, THIS IS WITH THE FLOW.
23.4	CRACKED/BROKEN JOINT			
73.8	DIRT/DEBRI	LIGHT	BOTTOM OF PIPE	
96.5	ROOTS AT JOINT	LIGHT		
100.4	ROOTS AT JOINT	LIGHT		
104.4	ROOTS AT JOINT	LIGHT		
108	ROOTS AT JOINT	LIGHT		
116.9	DIRT/DEBRI	2-4"	BOTTOM OF PIPE	
137.6	ROOTS AT JOINT	LIGHT		
153.9	ROOTS AT JOINT	LIGHT		
162.7	DEBRI	SMALL		
183.5	DIRT/DEBRI	1-2"	BOTTOM OF PIPE	
206.3	DIRT/DEBRI	2-4"	BOTTOM OF PIPE	
210.5	ROOTS AT JOINT	LIGHT		
259.2	DIRT/DEBRI	1-2"	BOTTOM OF PIPE	
335				CENTER OF MH-060008