



**Stack Bros.**  
3119 Hill Ave. Superior WI

Tel: 7153982964  
Fax:  
E-mail:

## Inspection Report

OT060020-ST060024

Date <b>8/9/2024</b>	P/O. No.	Weather <b>Dry</b>	Surveyor's Name <b>Josh Gordon</b>	Pipe Segment Reference <del>ST060024</del> - <del>OT060020</del>	Section No. <b>1</b>
Certificate No. <b>U-215-06023623</b>	Survey Customer	System Owner	Preset :	Pre-Cleaning <b>Jetting</b>	Sewer Category

Street <b>On Belknap BTW New York &amp; City of Superior</b>	Use of Sewer <b>Stormwater</b>	Upstream MH <b>ST060024</b>
City <b>City of Superior</b>	Drainage Area <b>District 6</b>	Downstream MH <b>OT060020</b>
Loc. details	Flow Control	Dir. of Survey <b>Downstream</b>
Location Code <b>Yard</b>	Length surveyed <b>402.46 ft</b>	Section Length <b>402.46 ft</b>

Purpose of Survey <b>Maintenance Related</b>	Joint Length <b>24 inch</b>
Year Laid	Dia./Height <b>Corrugated Metal Pipe</b>
Year Rehabilitated <b>1000</b>	Material
Tape / Media No. <b>000</b>	Lining Method

Add. Information :

1:1008	Position	Code	Observation	Photo	Grade
		ACB	Catch Basin, ST060024 / ST060024		
	0.00	MWL	Water Level, 5 %of cross sectional area		
	402.46	MSA	Survey Abandoned, deposits settled 35-40% / deposits settled 35-40%		

QSR	QMR	SPR	MPR	OPR	SPRI	MPRI	OPRI
0000	0000	0	0	0	0	0	0