

City of Superior-Wastewater Division: Pipe Televising Report

Televised by: Northern Pipe Equipment
Reviewed by: Chris Carlson
Date Televised: Monday, November 3rd 2003 – Thursday, November 6th 2003
Tape No: 250 S: 01:38:28 E: 01:56:13
Time Starting: 15:30 AM/PM 251 00:00:00 00:01:35
Time Finished: _____ AM/PM

Weather Condition:

Precipitation: ☒ None ☐ Light ☐ Heavy Temperature: 25 °F.
Conditions: ☐ Clear ☐ Partly Cloudy ☒ Cloudy ☐ Stormy

Line ID: MH06112A-MH060114
Location: ST ALBANS RD
Length: PL: 300' _____' Pipe Sections
Pipe Diameter: PD: 10" _____"
Pipe Material: ☐ PVC ☒ VCP ☐ RCP ☐ Other: _____
Flow: ☒ None ☐ Low ☐ 1/2 pipe ☐ 3/4 pipe
Televising Direction: ☐ Upstream ☒ Downstream

Footage Observations

0' @ MH 060114

09'	Set footage counter	
24'	wye tap crack / <u>12</u> o/c / in-service capped	<u>HAIRLINE CONTINUING</u>
72'	wye tap crack / <u>12</u> o/c / in-service capped	<u>CRACKS END</u>
87'	wye tap crack / <u>12</u> o/c / in-service capped	<u>9, 12, 3</u>
97'	wye tap crack / <u>12</u> o/c / in-service capped	<u>CRACKS END</u>
102'	wye tap crack / <u>12</u> o/c / in-service capped	<u>9, 12, 3</u>
121'	wye tap crack / <u>12</u> o/c / in-service capped	<u>CRACKS END</u>
199'	wye tap crack / <u>12</u> o/c / in-service capped	<u>SOUTH</u>
202'	wye tap crack / <u>10</u> o/c / in-service capped	
239'	wye tap crack / <u>10</u> o/c / in-service capped	
246'	wye tap crack / <u>10</u> o/c / in-service capped	<u>9, 12, 3</u>
246'	wye tap crack / <u>10</u> o/c / in-service capped	<u>DRIP JOINT</u>
258'	wye tap crack / <u>10</u> o/c / in-service capped	<u>9, 12, 3 LARGE</u>
272'	wye tap crack / <u>10</u> o/c / in-service capped	<u>CRACKS END</u>
288'	wye tap crack / <u>10</u> o/c / in-service capped	<u>DIPS 1/4</u>
301'	wye tap crack / <u>10</u> o/c / in-service capped	
307'	wye tap crack / <u>10</u> o/c / in-service capped	<u>9, 12, 3</u>
313'	wye tap crack / <u>10</u> o/c / in-service capped	<u>CRACKS END</u>
316'	wye tap crack / <u>10</u> o/c / in-service capped	
317'	wye tap crack / <u>10</u> o/c / in-service capped	<u>ROOTS @ JOINT CONTINUING</u>
318'	wye tap crack / <u>10</u> o/c / in-service capped	<u>w/ ROOTS</u>
325'	wye tap crack / <u>10</u> o/c / in-service capped	<u>w/ ROOTS</u>
329'	wye tap crack / <u>10</u> o/c / in-service capped	<u>ROOTS END</u>
360'	wye tap crack / <u>10</u> o/c / in-service capped	<u>ROOTS (2) JOINTS</u>
418'	wye tap crack / <u>10</u> o/c / in-service capped	<u>PROTRUDE 3" : UNABLE TO PROCEED</u>

REVERSE

City of Superior-Wastewater Division: Pipe Televising Report

[illegible]